DATE: 16 May 17

EQUIPMENT MAINTENANCE AND INSPECTION WORKSHEET

DA FORM 5988-E

UIC: W1D5ZZ

---------- EQUIPMENT DATA ----------

ADMIN NUM: D-27
EQUIP MODEL: M998HMMWV
EQUIP NOUN: TRK,UTILITY:CARGO/TRO(
EQUIP NSN: 2320-01-107-7155

EQUIP SERIAL NUM: AA-1B-1
REGISTRATION NUM: A1234B567
TYPE INSPECTION: PMCS
CURRENT READING: 21,000 MILES

	NUMBER	DATE	CHANGE NUMBER
PUBLICATION:	TM 9-2320-280-10	JAN 96	CHANGE 1
PUBLICATION:			

INSPECTOR LIC#:_____ TIME:_____ SIGNATURE:_____ TIME:_____

---------- PARTS REQUESTED ----------

FAULT	DOC NUM	NIIN	QTY DUE/REC	STATUS DATE	DATE COMP	PRI	DLC

---------- MAINTENANCE FAULTS ----------

ITEM NUM	FAULT DATE	FAULT STATUS	FAULT DESCRIPTION	CORRECTIVE ACTION	INITIALS
1	16 May 17	X	Class I brake fluid leak on D/S front wheel area		
2	16 May 17		D/S rear tire needs air	Tire pressure adjusted	
5	16 May 17	/	Dinner-plate sized dent on right side of vehicle		
6	16 May 17		R/S rear tire needs air	Tire pressure adjusted	
7.1	16 May 17		Power Steering Reservoir is too full	Operator corrected	
9	16 May 17	X	Front seatbelts look very frayed	Order new seatbelts IAW AR385-10	
10	16 May 17	X	Fire extinguisher is missing seal		
12	16 May 17		Coolant temperature reads 200 degrees °F	Not a fault, within tolerance	
17	16 May 17	X	Oil pressure guage reads 5 psi at idle	Operator corrected	
18	16 May 17	X	Brakes grab		
23	16 May 17		Transmission fluid is visible but below cross-		
			hatch marks	Operator Corrected	
26	16 May 17	/	L/S mirror is unserviceable	Defer to Motor SGT	
				or may be NMC depending	
				on severity IAW AR 385-10	