DATE: 16 May 17

EQUIPMENT MAINTENANCE AND INSPECTION WORKSHEET

DA FORM 5988-E

UIC: W1D5ZZ

---------- EQUIPMENT DATA ----------

ADMIN NUM: D-27
EQUIP MODEL: M998HMMWV
EQUIP NOUN: TRK,UTILITY:CARGO/TRO
EQUIP NSN: 2320-01-107-7155

EQUIP SERIAL NUM: AA-1B-1
REGISTRATION NUM: A1234B567
TYPE INSPECTION: PMCS
CURRENT READING: 21,000 MILES

	NUMBER	DATE	CHANGE NUMBER
PUBLICATION:	TM 9-2320-280-10	JAN 96	CHANGE 1
PUBLICATION:			

INSPECTOR LIC#:_____ TIME:_____ SIGNATURE:_____ TIME:_____

---------- PARTS REQUESTED ----------

FAULT	DOC NUM	NIIN	QTY DUE/REC	STATUS DATE	COMP PRI	DLC

---------- MAINTENANCE FAULTS ----------

ITEM NUM	FAULT DATE	FAULT STATUS	FAULT DESCRIPTION	CORRECTIVE ACTION	INITIALS
1	16 May 17		Class I brake fluid leak on D/S front wheel area		
2	16 May 17		D/S rear tire needs air		
5	16 May 17		Dinner-plate sized dent on right side of vehicle		
6	16 May 17		R/S rear tire needs air		
7.1	16 May 17		Power Steering Reservoir is too full		
9	16 May 17		Front seatbelts look very frayed		
10	16 May 17		Fire extinguisher is missing seal		
12	16 May 17		Coolant temperature reads 200 degrees °F		
17	16 May 17		Oil pressure guage reads 5 psi at idle		
18	16 May 17		Brakes grab		
23	16 May 17		Transmission fluid is visible but below cross-		
			hatch marks		
26	16 May 17		L/S mirror is unserviceable		